


Where asbestos materials can be found in a residential property



Usually licensed

- 1 Pipe lagging
- 2 Loose fill insulation
- 3 AIB airing cupboard and/or sprayed insulation coating on boiler and hot water tank
- 4 AIB soffits

Normally non-licensed

(If work that causes significant break up may require notification)

- 5 Asbestos cement water tank
- 6 Toilet seat and cistern
- 7 Vinyl floor tiles

- 8 Textured decorative coating on walls and ceilings eg Artex
- 9 Roofing felt
- 10 Asbestos cement panels
- 11 Asbestos cement soffits
- 12 Asbestos cement roof
- 13 Asbestos cement gutters and downpipes

If short duration non-licensed – otherwise licensed

- 14 AIB ceiling tiles
- 15 AIB bath panel
- 16 AIB behind fuse box

- 17 AIB partition wall
- 18 AIB interior window panel
- 19 AIB exterior window panel
- 20 AIB behind fire
- 21 AIB around boilers, storage heaters and warm air heating systems

Note: This diagram does not show all possible uses and locations of asbestos materials. A detailed survey will be required to identify all asbestos materials in a building.

AIB = Asbestos insulating board